## Part 573 Safety Recall Report

Navistar, Inc.
NOV 19, 2020
20V-494
20507

#### **Manufacturer Information :**

Manufacturer Name : Navistar, Inc. Address : 2701 Navistar Drive Lisle IL 60532 Company phone : 331-332-1590

### Vehicle Information :

	2020-2021 International HX BUSES, MEDIUM & HEAVY VEHICLES OTHER		
Power Train :			
Descriptive Information :	<ul> <li>14WNM or 14WNY (Axl</li> <li>The suspect vehicle da axle assemblies manufa 04/30/2020.</li> <li>The vehicles in the sur 14WNY (Axle; lift type 2 subject to this recall do</li> </ul>	le; lift type 20,000 lb. capac ates of manufacture were d actured by Watson and Chal spect population were buil	etermined by trucks built with lift lin on 06/01/2019 through t with feature code 14WNM or or axle) and all other vehicles not
Production Dates :	JUN 13, 2019 - MAY 27, 1	2020	
VIN Range 1: H	Begin : NR	End: NR	□ Not sequential



Number of potentially involved :

Estimated percentage with defect : 66%

**Population :** 

80

### 20V-494

# Part 573 Safety Recall Report

	<ul> <li>DIESEL</li> <li>The suspect population is identified by models equipped with Navistar feature code 14WNM or 14WNY (Axle; lift type 20,000 lb. capacity self-steer axle).</li> <li>The suspect vehicle dates of manufacture were determined by trucks built with lift axle assemblies manufactured by Watson and Chalin on 06/01/2019 through 04/30/2020.</li> <li>The vehicles in the suspect population were built with feature code 14WNM or 14WNY (Axle; lift type 20,000 lb. capacity self-steer axle) and all other vehicles not subject to this recall do not include this feature.</li> <li>There are 16 affected VX series trucks in the suspect population.</li> </ul>			
-				
Production Dates : VIN Range 1 :		) - NOV 25, 20 NR	D19 End: NR	Not sequential
escription of Defect :	ot · • The low	or roor pivo	t can carry that connect the	e trailing arm to the steerable
	auxiliary feature o • Extende loss of th	lift axle may f the corresp ed use of the e cap screw a	r not be long enough to suffic onding nuts. suspension in this condition and related washers and nut on the roadway.	iently engage the locking can result in the fracture or
	1: NR			
			f the cap screw resulting in fo the risk of a vehicle crash ar	
Description of the Caus			specified in design did not m rresponding lock nut.	eet the required thread
dentification of Any Warn that can Occu	0			
volved Components :				
Component Name 1	: Lift axle piv	ot cap screv	V	
<b>Component Description</b>	: Bolt			
Component Part Number	: Supplier P/	′N 19800-11		

### **Supplier Identification :**

### **Component Manufacturer**

Name: Watson and Chalin Specialty Products (Wa

Address : 725 E. University Dr. McKinney Texas 75069

Country: United States

### Chronology :

- $\bullet$  07/06/2020 Navistar receives communication from Watson and Chalin describing the issue with lower rear pivot cap screws.
- $\bullet$  07/14/2020 Navistar discusses the issue with Watson and Chalin and initiates an investigation to determine impact to Navistar products.
- 07/24/2020 Navistar determines the suspect population and meets with Watson and Chalin to determine potential failure modes and severity of failures.
- 07/28/2020 Watson and Chalin informs Navistar their intent to submit an Equipment 573 report to NHTSA.
- $\cdot$  08/04/2020 Navistar engineering and quality meet with Watson and Chalin to understand root cause and the effects of the failure.
- 08/13/2020 Navistar declares a Safety Recall.
- 10/23/2020 Watson and Chalin informs Navistar that about expanding their recall 20E055.
- 10/26/2020 Navistar and Watson and Chalin meet to determine the impact to Navistar products.
- 11/04/2020 Navistar and Watson and Chalin finalize the expanded suspect population.
- 11/12/2020 Navistar approves expanding recall 20507 (NHTSA Recall 20V-494).

### **Description of Remedy :**

Description of Remedy Program :	<ul> <li>The remedy will involve replacing all lower rear pivot cap screws and associated nuts and washers.</li> <li>Navistar's plan for reimbursement of pre-notification remedies, on file with NHTSA and dated 10/03/2018, applies and reimbursement instructions will be included in the customer notification.</li> </ul>
	The remedy cap screws are of sufficient length to maintain proper clamp load where the recalled cap screws are not.
0	reported by Watson and Chalin in their 573 Report; Watson and Chalin engineering and manufacturing implemented a corrective change from an 11.5 inch nominal length cap screw to a 12.0 inch nominal length cap screw on 05/01/2020.

Recall Schedule :	
Description of Recall Schedule :	It is estimated that the Customer and Dealer notification letters will be mailed by $10/12/2020$ . mailing to owners of additional population to be mailed on $11/23/2020$
Planned Dealer Notification Date :	
Planned Owner Notification Date :	OCT 12, 2020 - NOV 23, 2020

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573