

Part 573 Safety Recall Report

22V-409

Manufacturer Name : Ferrara Fire Apparatus, Inc.**Submission Date :** JUN 21, 2022**NHTSA Recall No. :** 22V-409**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Ferrara Fire Apparatus, Inc.

Number of potentially involved : 22

Address : 27855 James Chapel Road
PO Box 249 Holden LA 70744

Estimated percentage with defect : 100 %

Company phone : 800-443-9006

Vehicle Information :

Vehicle 1 : 2021-2023 Ferrara Inferno, Igniter

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : All units under this part number are part of the recall as they share the same build issue. Similar units with a different part number were built to specification and are not part of the recall population.

There are approximately 72 units delivered under a private label to a single OEM customer and approximately 788 units delivered to other affected OEMs.
The

Production Dates : MAR 29, 2022 - MAY 10, 2022

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : Weldon, a division of Akron Brass Company, produces Node, an electrical multiplex module, under both a private label to a single customer as well as to multiple OEMs for installation in emergency vehicles. In the affected products, the Node contains a termination resistor installed on the node circuit board instead of the termination resistor being installed only within the electrical harness. If the vehicle network design has not accounted for this additional resistor, it may reduce the bus resistance below the defined tolerance levels and may lead to a loss of data on the CAN network. Installations with multiple nodes are more likely to experience the condition.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the bus resistance is reduced, the CAN network connection could fail which may interrupt the transfer of data on this connection. If the CAN network connection is interrupted or fails and depending on how the vehicle's

electrical systems are designed, it may impact the operation of various electrical loads controlled by the Node, including vehicle lighting, which may increase the risk of a crash.

Description of the Cause : Due to a bill of material error, a resistor was installed in error on the printed circuit board.

Identification of Any Warning NONE
that can Occur :

Involved Components :

Component Name 1 : V-mux Hercules HC Node 1.5

Component Description : Multiplex Input / Output Node for Weldon V-mux compatible systems

Component Part Number : 6060-1000-00

Supplier Identification :

Component Manufacturer

Name : Weldon Division of Akron Brass

Address : 3656 Paragon Drive
Columbus Ohio 43228

Country : United States

Chronology :

Refer to NHTSA Recall 22E-037 below for Weldon's chronology.

On April 29, 2022, Weldon was contacted by an OEM that described an issue with the CAN connection when installing the Node. Weldon was able to isolate the issue to the inclusion of the additional termination resistor on the circuit board. Weldon stopped the shipment of additional units. On May 2, 2022, Weldon reviewed the technical details affecting the Node to confirm the issue, considered whether the same issue impacts any similar products and decided to conduct a safety recall. On May 3, 2022, Weldon determined a recent shipment of a variation of the Node sold under a private label and to a single customer was also impacted. Weldon confirmed with the customer these units had never been installed in a vehicle and remained in the customer's inventory. Weldon secured all of the affected products from the customer's inventory and on May 4, 2022 reworked those units to remove the additional resistor.

On May 16, 2022, Ferrara Fire received communication from Weldon about recall 22E-037 for their V-mux Hercules HC Node 1.5. On May XX, 2022, it was agreed that Ferrara Fire should file a Part 573

May 16, 2022 – Escalated the issue to REV Group Management.

May XX, 2022 – REV's senior leadership approved a voluntary recall for this issue.
Identify the

Description of Remedy :

| | |
|--|--|
| Description of Remedy Program : | Weldon will notify affected customers and ask them to return any affected product that remains in their inventory to Weldon to be reworked. Affected OEMs will notify vehicle purchasers and Weldon will provide replacement units and reimburse for labor costs. The affected product sold under the private label have already been remedied |
| How Remedy Component Differs from Recalled Component : | The remedy component will have the additional termination resistor removed from the circuit board. |
| Identify How/When Recall Condition was Corrected in Production : | Existing inventory at Weldon was isolated and shipments placed on hold on 4/29/2022, the same day the potential issue was first reported to Weldon. Any affected product in Weldon's inventory will be reworked and a new part number issued. |

Recall Schedule :

| | |
|------------------------------------|-----------------------------|
| Description of Recall Schedule : | NR |
| Planned Dealer Notification Date : | JUL 27, 2022 - JUL 29, 2022 |
| Planned Owner Notification Date : | AUG 01, 2022 - AUG 03, 2022 |

* NR - Not Reported