The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name : Braun Ambulances

Submission Date : JAN 08, 2021 NHTSA Recall No. : 21V-003

Manufacturer Information :

Manufacturer Recall No.: NR

Manufacturer Name : Braun Ambulances Address : 1170 Production Drive

Van Wert OH 45891 Company phone : 4192327020

Vehicle Information :

	2019-2021 Crest BUSES, MEDIUM		-		
Body Style :					
Power Train :	GAS				
Descriptive Information :	Includes all CCL 150 model vehicles produced with a CPR seat option, composed of a single side facing seating position, located on the street side of the ambulance patient compartment, with a six point belt. Vehicles not produced with the CPR seat option are not affected. 39 model year (MY) 2019 CCL150 models mounted on MY2019 Ford E-350 chassis with gas engines are affected. 7 MY2021 CCL150 models mounted on MY2021 Ford E-350 chassis with gas engines are affected.				
Production Dates :	OCT 04, 2019 - S	EP 17, 2020			
VIN Range 1:	Begin :	NR	End: NR	Not sequential	
Body Style : Power Train : Descriptive Information :	DIESEL Includes all CCL single side facing	g seating positio	cles produced with a CPR seat o on, located on the street side of t elt. Vehicles not produced with	he ambulance patient	
	are not affected. F-350 chassis wi MY2020 Ford F-	1 model year (1 ith diesel engine 350 chassis wit	MY) 2019 CCL150 model mount e is affected. 11 MY2020 CCL150 h diesel engines are affected.	ed on MY2019 Ford	
Production Dates :					
	Begin :	NR	End: NR	Not sequential	



Number of potentially involved :

Estimated percentage with defect :

Population :

NR

NR

21V-003

Part 573 Safety Recall Report

21V-003

Page 2

Vehicle 3:	2019-2020 Crestline	CCL150 Type III G-Series	
	BUSES, MEDIUM & H	• •	
Body Style :			
Power Train :	GAS		
Descriptive Information :	single side facing sea compartment, with are not affected. 1 m Chevrolet G3500 ch	ating position, located on the s	d. 2 MY202 CCL150 models
Production Dates :	APR 09, 2020 - OCT		
VIN Range 1:	Begin : NF	End: NR	☐ Not sequential
escription of Defect : Description of the Defe		rns two of the eight fastening j mbulance patient compartmen	
	position on the s the threaded ins	treet-side of the vehicle. There erts used for the rearward retr close to a mounting flange resu	
FMVSS	1: NR		
FMVSS	2: NR		
Description of the Safety Ris	loss of effectiven		ay result in partial or complete ich may increase the chance of n the event of a crash.
Description of the Caus	se: NR		
	ing A loose retractor ur : visible warning f	mounting bolt or shoulder bel or this condition.	t D-ring bolt can serve as a
volved Components :			
Component Name 1	: NR		
Component Description	: NR		
Component Part Number	: NR		

Part 573 Safety Recall Report

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program :	NR
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production ·	NR

Recall Schedule :

Description of Recall Schedule :	NR	
Planned Dealer Notification Date :	NR	- NR
Planned Owner Notification Date :	NR	- NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573

21V-003