Part 573 Safety Recall Report

Manufacturer Name :	Boise Mobile Equipment
Submission Date :	OCT 14, 2021
NHTSA Recall No. :	21V-669
Manufacturer Recall No. :	52606

Manufacturer Information :

N

Manufacturer Name : Boise Mobile Equipment Address : 5656 Morris Hill Rd Boise ID 83705 Company phone : 208 338 1444

Population :

Number of potentially involved : 1 Estimated percentage with defect : 100 %

云 🔨 🕰 🕁

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

21V-669

Vehicle Information :

Vehicle 1:	2016-2016 International 4	400 type 3 fire truck	
Vehicle Type :	BUSES, MEDIUM & HEAVY	VEHICLES	
Body Style :	4-DOOR		
Power Train :	DIESEL		
Descriptive Information :	We only purchased one set of the defective code 3 / ecco lights identified in recall 20e-041 and this was the vehicle they were used on.		
Production Dates :	DEC 15, 2015 - FEB 06, 201	16	
VIN Range 1:	Begin : NR	End: NR	☐ Not sequential

Description of Noncompliance :

Description of the
Noncompliance :The brake lamps (part# 79STTRBZ) exceed the maximum permissible candela
levels specified in Federal Motor Vehicle Safety Standard (FMVSS) No. 108 at
certain test points.FMVSS 1 :
FMVSS 2 :108 - Lamps, reflective devices, and assoc. Equipment
NRDescription of the Safety Risk 2The increased photometric intensity does not comply with the requirements
of FMVSS 108 and may adversely affect the vision of following drivers,
increasing the risk of a vehicle crash without warning.Description of the Cause :The lamps do not meet the requirements of the relevant standard.Identification of Any Warning
that can Occur :NR

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

21V-669

Component Name 1 : Stop tail turn light Component Description : Stop tail turn light Component Part Number : 79STTRBZ

Supplier Identification :

Component Manufacturer

Name : Ecco holdings corp Address : 833 West Diamond Boise Idaho 83705 Country : United States

Chronology:

On August 16th Boise Mobile was notified of a defect involving a stop tail turn light used on a vehicle built in 2016. The light does not meet Federal Motor Vehicle Safety Standard (FMVSS) No. 108 at certain test points. So we are initiating the recall/ repair of this vehicle.

Description of Remedy :

Description of Remedy Program :	Boise Mobile will assist the affected customer in reaching out to Code 3 / Ecco Group directly to request two filter kits (Part number CZ0199) free of charge that will ensure that the lamps perform within the permissible photometric intensity ranges.
U I	The remedy involves installation a filter kit that will ensure that the lamps perform within the permissible photometric intensity ranges.
Identify How/When Recall Condition was Corrected in Production :	There was no subsequent use of the light in question.

Recall Schedule :

Description of Recall Schedule :	NR
Planned Dealer Notification Date :	SEP 09, 2021 - SEP 23, 2021
Planned Owner Notification Date :	SEP 09, 2021 - SEP 23, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573