

Heartland Front Reflector

Description

It has been decided the vehicles in this recall population may have been manufactured without the forward reflector on the front of the camper.

Inspection & Repair

Identify the reflector locations on the front forward sidewall of the camper.

1. This is the correct locations of the reflector and side marker light on the fifth wheel.



Forward Side marker light
located on both side walls

Forward Sidewall reflector
should be mount in this location.
On both sidewalls.

2. Where to install the reflector that is being sent to you.



3. Location to install the reflector, place one on each side (preferably on the skirting) any position in this general area is acceptable as long as the reflector is below 60"
4. Clean any dirt from the sidewall, peel backing from tape and apply. Screws can be applied for additional strength.

Parts

Reflector # 49235

Warranty

Dealers installing the Reflector may file Recall Repair warranty claim using warranty code 99.01.43.L, for 0.1 hours for the inspection. If reflectors are required than an additional 0.1 hours for the reflectors.

Please refer all questions and authorization requests to Heartland Warranty/Service Department. 877-262-8032