

Part 573 Safety Recall Report

20E-058

Manufacturer Name : Firefly Integrations, LLC**Submission Date :** SEP 21, 2020**NHTSA Recall No. :** 20E-058**Manufacturer Recall No. :** NR**Manufacturer Information :****Manufacturer Name :** Firefly Integrations, LLC**Address :** 1013 Elroy Drive
Middlebury IN 46540**Company phone :** (574) 825-4600**Population :****Number of potentially involved :** 2,682**Estimated percentage with defect :** 100 %**Equipment Information :****Brand / Trade 1 :** Multiplex**Model :** G9**Part No. :** To Be Determined**Size :** NR**Function :** NR**Descriptive Information :** Recall population to include all and only RV units which use a G9 electronic control module.**Production Dates :** OCT 01, 2017 - AUG 20, 2020**Description of Defect :****Description of the Defect :** G9 unit can fail if excessive voltage is applied.**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** Potential thermal event.**Description of the Cause :** NR**Identification of Any Warning** NR
that can Occur :**Involved Components :**

Component Name : G9

Component Description : Control circuit Board

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported