## **Recall Quarterly Report**

20V-451

Manufacturer Name : Triumph Motorcycles America, Ltd. NHTSA Recall No. / MFR Recall No. : 20V-451 /SRAN 582 Recall Subject : Reflex Reflector May Detach/FMVSS 108 Owner Notification Beginning Date : AUG 19, 2020 Owner Notification End Date: AUG 19, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 13, 2021	2021-1	603	411	0	0
2	JAN 19, 2021	2020-4	603	380	0	0
1	OCT 09, 2020	2020-3	603	267	0	0

This Document Last Updated : APR 16, 2021

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.