Recall Quarterly Report

20V-605

Manufacturer Name: Forest River, Inc.

NHTSA Recall No. / MFR Recall No.: 20V-605 /51-1237 Recall Subject: P2K Bunk System Inner Gear May Fail Owner Notification Beginning Date: NOV 06, 2020

Owner Notification End Date: NOV 06, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 25, 2021	2021-3	67	42	0	0
3	JUL 15, 2021	2021-2	67	36	0	0
2	APR 20, 2021	2021-1	67	24	0	0
1	JAN 18, 2021	2020-4	67	7	0	0

This Document Last Updated: OCT 26, 2021

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.